



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D2652**Job Sheet 208601****Part No:** D2652**Job Qty:** 400 pcs**Part Name:** Bushing**Part Weight:** 0 lbs**Status:** New**Priority:** Medium**Job Created:** 3/26/20**Job Tracking No:****Due Date:** 5/12/20**Created By:** Marie Lajeunesse**Type:** SOLD**Description:****Note:** DWG REV A IPP Rev:B 02.06.13 Now machined in house. NG**Ship Via:****Bill of Materials****Job Routing**

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier	DAS	Sign-off
					Setup Hrs	Run Hrs			
100	Hardinge - 1	400 pcs	5/12/20	5/12/20	0.50	14.72	Hardinge - 1	33	20/04/25
110	QC 2	400 pcs	5/12/20	5/12/20	0.00	0.00	QC 2 - 1	9-89	
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33	DAS 33	20/04/25
							QC 2 - 35	9-89	
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		
							QC 2 - 8		
							QC 2 - 66		
							QC 2 - 64		
							QC 2 - 65		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 813 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S273336**Part:** D2652**Job No:** 208601**Serial No/Batch:** S273336**Revision:****Inspector:****Exp Date:****Instructions:** Various STC's**Date:** 04/25/20

120	QC 8	400 pcs	5/12/20	0.00	0.00	QC 2 - 5	
						QC 2 - 71	
						QC 2 - 73	
						QC 2 - 69	
						QC 2 - 76	
						QC 2 - 86	
						QC 8 - 12	
						QC 8 - 14	
						QC 8 - 17	
						QC 8 - 20	
						QC 8 - 25	
						QC 8 - 3	
						QC 8 - 32	
						QC 8 - 33	
						QC 8 - 35	
						QC 8 - 39	
						QC 8 - 4	
						QC 8 - 44	
						QC 8 - 45	
						QC 8 - 49	
						QC 8 - 58	
						QC 8 - 8	
						QC 8 - 9	
						QC 8 - 68	
						QC 8 - 67	
						QC 8 - 1 (A)	
						QC 8 - 47	
						QC 8 - 40	
						QC 8 - 52	
						QC 8 - 23	
						QC 8 - 57	
						QC 8 - 76	
						QC 8 - 61	
						QC 8 - 66	
130	Packaging 3-1 - Stock - B4B	400 pcs	5/12/20	0.00	0.00	Packaging 3 - 1 - B4B	
						Packaging 3 - 2 - B4B	
						Packaging 3 - 3 - B4B	
						Packaging 3 - 4 - B4B	
						Packaging 3 - 5 - B4B	
						Packaging 3 - 6 - B4B	
						Packaging 3 - 7 - B4B	
						Packaging 3 - 8 - B4B	
						Packaging 3 - 9 - B4B	
						Packaging 3 - 10 - B4B	
						Packaging 3 - 11 - B4B	
						Packaging 3 - 12 - B4B	
						Packaging 3 - 13 - B4B	
						Packaging 3 - 14 - B4B	
						Packaging 3 - 15 - B4B	
						Packaging 3 - 16 - B4B	
						Packaging 3 - 17 - B4B	
						Packaging 3 - 18 - B4B	
						Packaging 3 - 19 - B4B	
						Packaging 3 - 20 - B4B	
						Packaging 3 - 21 - B4B	
						Packaging 3 - 22 - B4B	
						Packaging 3 - 23 - B4B	
						Packaging 3 - 24 - B4B	
						Packaging 3 - 25 - B4B	

VHS 10/4/29

DAS
28
9-89

140 QC 21 - SA

400 pcs

5/12/20

0.00 0.00

Packaging 3 - 26 - B4B
 Packaging 3 - 27 - B4B
 Packaging 3 - 28 - B4B
 Packaging 3 - 29 - B4B
 Packaging 3 - 30 - B4B
 Packaging 3 - 31 - B4B
 Packaging 3 - 32 - B4B
 Packaging 3 - 33 - B4B
 Packaging 3 - 34 - B4B
 Packaging 3 - 35 - B4B
 Packaging 3 - 36 - B4B
 Packaging 3 - 37 - B4B

QC 21 - SA - 21

QC 21 - SA - 70

QC 21 - SA - 53

Broussard

APR 29 2020

DAS

70

9-89

Part Op 100 - (Hardinge) 1-TURN AS PER FOLIO FA252 & DWG D2652
 Descriptions: 110 - (QC2- Inspect parts off machine FA/FAIB)
 120 - (QC8- Inspect parts - second check)
 130 - (Identify as per dwg & Stock Location: _____)
 140 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
M303R0.500	303 Round Bar 0.500"	23.2000 ft (.058 ea)	100-Hardinge - 1	S 267900

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Hardinge - 1	M303R0.500	23	49	0

Part Specifications

Spec No	Description	Target/Tolerance	Limits	Type	Special Comments
1	Bushing	0.600inches ± 0.010	0.610 0.590		
2	Bushing	0.060inches ± 0.005	0.065 0.055		
3	Bushing	0.305inches + 0.000 - 0.002	0.305 0.303		
4	Bushing	0.191inches + 0.005 - 0.001	0.196 0.190		
5	Bushing	0.500inches ± 0.010	0.510 0.490		
6	Bushing	0.030inches ± 0.010	0.040 0.020		
7	Bushing	20.000Degrees ± 0.010	20.010 19.990		
8	Bushing	0.010inches + 0.010 - 0.000	0.020 0.010		

Plex 3/26/20 9:09 AM Dart.lajeunesse.marie

Date:

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE



NCR No.

Route update only

Job: _____ Part No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐		DEPARTMENT/PROCESS Skid-tube Machining ☐ Large Fab ☐ Cross tube Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering Water Jet ☐ Supplier ☐ Quality ☐		Route update only ☐		AEROSPACE																													
Date: _____		Sequence #: _____		QTY Affected: _____		MRB (QS1042)																															
Description Work Order Deviation				Disposition																																	
								Completed By																													
								Lead hand / Supervisor																													
								QC / QA Coordinator																													
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐				FAULT CATEGORY <table border="1"> <tr> <td>Pressure/Forced</td> <td>Contamination</td> <td>Power Loss/Surge</td> <td>Positioned Wrong</td> </tr> <tr> <td>Bending</td> <td>Misaligned/off center</td> <td>Folio/Program</td> <td>Outside Tolerance</td> </tr> <tr> <td>Crushing</td> <td>BOM/Route</td> <td>Grain Direction</td> <td>Drawing</td> </tr> <tr> <td>Cracks</td> <td>Broken/Damage/Defect</td> <td>Weld</td> <td>Finish</td> </tr> <tr> <td>Crimp/Kink/Ripple/Wave/Twist</td> <td>Incomplete/Unclear Instructions</td> <td>Wrong Stock Pulled</td> <td>Part Lost/Missing</td> </tr> <tr> <td>Marks/Chatter</td> <td>Drill Holes</td> <td>Out of Sequence</td> <td>Misread</td> </tr> <tr> <td>Mislabeled</td> <td>Fit/Function</td> <td>Off-set/Set-up</td> <td></td> </tr> </table>						Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong	Bending	Misaligned/off center	Folio/Program	Outside Tolerance	Crushing	BOM/Route	Grain Direction	Drawing	Cracks	Broken/Damage/Defect	Weld	Finish	Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing	Marks/Chatter	Drill Holes	Out of Sequence	Misread	Mislabeled	Fit/Function	Off-set/Set-up	
Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong																																		
Bending	Misaligned/off center	Folio/Program	Outside Tolerance																																		
Crushing	BOM/Route	Grain Direction	Drawing																																		
Cracks	Broken/Damage/Defect	Weld	Finish																																		
Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing																																		
Marks/Chatter	Drill Holes	Out of Sequence	Misread																																		
Mislabeled	Fit/Function	Off-set/Set-up																																			
				Other/Details:																																	